

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**


**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

31/2010 11:45am 7.0.0.0  
SELF CONTAINED VACUUM

BOOM

SELF CONTAINED, 360 degree ROTATION,  
EXTENDABLE BOOM ARM, VACUUM HOSE,  
to mount on a VACUUM CONTAINER

FIG. 1



## FIG. 2

BOOM  
TURN  
TABLE  
16

LUBRICANT  
SEAL  
17

SEAL 15

BOOM  
ATTACHMENT  
TO VACUUM  
TANK 14


VACUUM CONTAINER  
ACCESS COLLAR 19

10 TO VACUUM PUMP

STABALIZER  
13

BALL  
FLOAT  
11

FIG. 3



SELF CONTAINED VACUUM  
BOOM

FIG. 4

SELF CONTAINED, 360 degree ROTATION,  
EXTENDABLE BOOM ARM, VACUUM HOSE,  
to mount on a VACUUM CONTAINER

